

PROW IDENTITY	PROW TYPE	LOCATION	LANDOWNER	CONDITION	ACTIONS
CHER1	Bridleway	From road up to Red Barn by Dandy Highwayman.		Overgrown & sign missing.	Dave Grafton to cut back. PC to contact WC for replacement sign.
CHER2	Bridleway	Chalk path opposite Park Lane up to downs.	Richard Gantlet	Very steep slippery chalk surface. Advertised on bus's as best access to downs. Also overgrown with drainage issues.	Parish clerk has contacted bus company to ask for change in advertising advising other safe and easier routes up onto downs, awaiting response. PC obtaining quote for cutting back growth. Dave Grafton to investigate with landowners putting in drainage.
CHER3	Bridleway	Poachers Croft up to downs.		Path low so reduced visibility. Access from A4 is a very steep drop which WC (Stephen Leonard), is aware of.	Walk and liaise with WC.
CHER4	Bridleway going onto Byway		Richard Gantlet	Stile broken and gate leaning over.	PC to investigate further and talk with landowner on repair.
CHER5	Bridleway				Audit TBC
CHER6	Byway				Audit TBC
CHER6A	Bridleway			Wet and overgrown, sign missing.	PC to investigate and contact WC for replacement sign.
CHER7	Footpath				Audit TBC
CHER8	Footpath			Re-routed by Rob Pickford.	Route clear and usable.
CHER9	Footpath				Audit TBC

PROW IDENTITY	PROW TYPE	LOCATION	LANDOWNER	CONDITION	ACTIONS
CHER10	Footpath				Audit TBC
CHER21	Bridleway			Overgrown and used by motorbikes.	Investigate further.
CHER22	Bridleway				Audit TBC
CHER23	Footpath			Map incorrect as now rerouted due to sand mountain.	PC to report to WC for map update.
CHER24	Bridleway			Map incorrect as now rerouted due to sand mountain.	PC to report to WC for map update.
CHER26	Footpath				Audit TBC
CHER27	Footpath			Historically permissive use was given for horses over this route. Horse riders and cyclists use footpath which is very narrow and overgrown leading to concerns from walkers about meeting horse riders & cyclists on the route. A stile at the top end completely buried in brambles. Gate to side of stile now permanently unlocked.	PC to organise keeping the route as clear and wide as possible by cutting back for the rest of the growing season. Walkers still want footpath status reinstated. Volunteers to free stile. PC to talk with landowners and WC and monitor use by horses over next month. Agreed signs need to be erected to notify route has permissive use by horses and cyclists.
CHER28	Footpath				Audit TBC
CHER29	Footpath				Audit TBC
CHER30	Bridleway				Audit TBC
CHER32	Footpath				Route clear and usable.

PROW IDENTITY	PROW TYPE	LOCATION	LANDOWNER	CONDITION	ACTIONS
CHER33	Bridleway			Map incorrect as now rerouted due to sand mountain.	PC to report to WC for map update.
CHER34	Footpath				Audit TBC
CHER35	Bridleway				Audit TBC
CHER36	Footpath				Audit TBC
CHER37	Footpath				Audit TBC

**If anyone has further information on any of the above routes please contact
Peter Johnson at clerk@cherhill.org.**