

PROW IDENTITY	PROW TYPE	LOCATION	LANDOWNER	CONDITION	ACTIONS
CHER11	Bridleway	Starts from Lymers close, right after bridge and meets CHER20 and WMON9	Richard Gantlett	Narrow for horse riders on first part but clear of weed growth, good hard ballast surface once over bridge.	None
CHER 11A	Footpath	Off right of CHER 11 across field next to ditch.	Richard Gantlett	Narrow and lumpy.	None
CHER11B	Footpath	Off left from CHER11 over bridge, meets CHER 12A	Richard Gantlett	Good wide clear path. Difficult stile and broken bridge at junction with CHER12A.	147 form completed by landowner and returned to WC PROW Officer. Parish Council to buy gates to replace stile and Dave Grafton to fit gates with help from volunteers and fit a culvert pipe in the ditch instead of a bridge with road planings over and hand rails if needed. Work to begin as soon as access is possible over wet ground.

PROW IDENTITY	PROW TYPE	LOCATION	LANDOWNER	CONDITION	ACTIONS
CHER12A	Route to avoid last part of CHER14 which becomes narrow fenced corridor, goes around field to meet CHER12.	Footpath	Richard Simpson/Richard Gantlett (stock owner)	Route blocked in places by self seeding bushes. Style at end broken with nails sticking out of broken handrail.	147 form completed by landowner with stock (Richard Gantlett). Work to commence to replace stile with gate and sort levels by Dave Grafton with volunteers as soon as access is possible over wet ground. WC PROW officer to meet with landowner Richard Simpson to discuss improvements to his side of route. Chased 08/08/24.
CHER 12	Footpath	Onwards from CHER12A to join CHER31 and CHER 20A	Richard Gantlett	Route clear and walkable.	None
CHER13	Bridleway	From Back Lane in Yatesbury to Nolands.	Richard Simpson	Route narrow from weed and hedgerow growth. No warning signs provided by landowner for forestry activity, fun rides and pheasant shoots.	WC PROW Officer to meet with landowner to try to resolve issues. Chased on 08/08/24.
CHER14	Footpath	From Yatesbury Lane past Stert pond to CHER12A.	Richard Simpson and Richard Gantlett.	Surface damaged from hedge cutting. Last part becomes narrow corridor with deer fencing posts broken so leaning into path. Hedges on either side growing through fencing and blocking route.	WC PROW Officer to meet with landowner to try to resolve issues. Chased on 08/08/24.

PROW IDENTITY	PROW TYPE	LOCATION	LANDOWNER	CONDITION	ACTIONS
CHER15	Bridleway	From Snakes Lane to CHER18 & AVEB18 (old cycle route)	Richard Gantlett and Ben Butler		Audit TBC
CHER16	Byway - Permissive only over first part.	From Snakes Lane through Little London and onto CHER20	Richard Gantlett	Large dip/hole in Snakes Lane that fills with water blocking route.	PC have contacted Richard Gantlett to ask for repair.
CHER17	Byway	First part of Yatesbury lane.	Richard Simpson	Tree trunk placed to block parking on byway at junction of CHER14.	WC PROW Officer to meet with landowner to try to resolve issues. Chased on 08/08/24.
CHER18	Byway	From Cooks plantation to Windmill Hill	?	WC has resurfaced recently.	Audit TBC
CHER19	Byway	Barrow Way, from The Avenue to CHER18.	Richard Gantlett and Rob Pickford.	Ditches need digging for water to drain as PROW is lower than ditch and floods in one part.	New Cycle route so LHFIC contacted to help raise PROW. PC need to contact landowners to clear ditches.
CHER20	Bridleway	From WMON9 to CHER20A & BBAS2.	Richard Gantlett	Two gates at either end of grassy lane between CHER16 and CHER11 are not horse friendly gates but span the bridleway. PROW sign tied up with twine by community member.	PC to contact landowner, further investigation and photos required.
CHER20A	Footpath	From CHER20 onwards to CHER12	Richard Gantlett	Audit TBC	
CHER 31	Footpath	From CHER12 to join Yatesbury Lane	Richard Gantlett	Overgrown	Dave Grafton has cut back up to kissing gate.

**If anyone has further information on any of the above routes please contact;
Peter Johnson at clerk@cherhill.org.**